National Justice Museum. The Shire Hall. Nottingham.Risk Assessment Record for: Transformer Room – Cave Workshops, Justice Reinvented,<br/>Capital Punishment Debate, Case StudyCompleted By:JADate:05/11/24Date for review:05/11/25

**Existing Precautions** No Task/Event Hazard Likelihood Severity Risk **Additional Action** Rating Required Transformer Room – Cave Injury arising from manual Carry out periodic Permit only fully trained 1 1 4 4 Workshops, Justice Reinvented, handling activity when staff members to carry out staff training Capital Punishment Debate, this operation. setting up. Case Study Slips, trips, and falls All groups under 2 0 supervision at all 2 2 4 No further action times. required. • Health and safety briefing given before activities commence. Designated access 0 routes. • Adequate lighting. • Passages and doorways kept clear. • Flagstone/ uneven flooring in good condition, with regular inspection. 3 Injury arising from falling • Very little stored at 1 Ensure staff are 4 4 objects or displays height aware of potential

		0 0	Single layer stacking on shelves Purpose manufactured stands & securements.				risk and will highlight anything they see immediately to management.
4	Electrocution	0	PAT tests undertaken Socket covers on exposed electrical sockets. Electrical equipment concealed	1	4	4	
5	Injury arising from outbreak of fire	0 0 0 0	Alternative exits available. Group always with a member of staff when in this area Fire warning system in full operation Fire drills regularly take place Instruction for in the event of a fire given to all groups at the beginning of the day. Site regularly inspected by fire service. Staff issued with radios to call for assistance if needed	2	3	6	No further action required
6	General discomfort	0	Group numbers limited to a maximum of 35.	1	2	2	No further action required

7	Injury or illness arising from inadequate welfare facilities	0 0	Appropriate number of toilets, washing, and rest facilities, situated in a close vicinity to the site Trained first aid availability.	2	2	4	No further action required.
8	Injury arising from attack	0 0 0 0	Secure area with restricted access to public. Office tenants only with access to the corridor next to the room. Pre- booked activities. Signage to deter entry	1	4	4	No further action required.

5X5 MATRIX METHOD:

Rating: 1 - 4 ACCEPTABLE - No further action required, but ensure control measures are maintained.

- 5 9 ADEQUATE Look for suitable improvements at the next review.
- 10 16 TOLERABLE Look to improve within a specified timescale.
- 17 25 UNACCEPTABLE Stop activity and make immediate improvements.