The SET test: Flush water bar.

Sustainable. Carefully fitted large rocks will remain in place a long time. Large steep drain needs minimal maintenance.

Effective. Backed with soil water cannot run between rocks. Large sweeping drain will be effective for a long time with minimal maintenance.

Traversable. Easy to step on or over onto landing, with steps down the back make this feature easily traversable



R. Fina 10.10.20