

The SET test: Water bars

Sustainable? No. While the rocks will last a long time, the intended purpose of diverting water from the trail did not.

Effective? No. Water runs between the stones. Water goes around following hiker bypass. No drain. No place for water to go except down the trail

Traversable? No. Too big to easily step over, most people go around causing trail widening and a water bypass.

